NTED STATES
RIMENT OF
WMERCE



National Bureau of Standards Library, E-01 Admin. Bldg.

NBS SPECIAL PUBLICATION 260-29

Standard Reference Materials:

CALIBRATION OF NBS
SECONDARY STANDARD MAGNETIC TAPE
(COMPUTER AMPLITUDE REFERENCE)
SRM 3200
USING THE REFERENCE TAPE
AMPLITUDE MEASUREMENT "PROCESS A"
MODEL II

U.S.
ARTMENT
OF
OMMERCE
National

National Bureau of Standards



NATIONAL BUREAU OF STANDARDS

The National Bureau of Standards was established by an act of Congress March 3. 1901. The Bureau's overall goal is to strengthen and advance the Nation's science and technology and facilitate their effective application for public benefit. To this end, the Bureau conducts research and provides: (1) a basis for the Nation's physical measurement system, (2) scientific and technological services for industry and government, (3) a technical basis for equity in trade, and (4) technical services to promote public safety. The Bureau consists of the Institute for Basic Standards, the Institute for Materials Research, the Institute for Applied Technology, the Center for Computer Sciences and Technology, and the Office for Information Programs.

THE INSTITUTE FOR BASIC STANDARDS provides the central basis within the United States of a complete and consistent system of physical measurement; coordinates that system with measurement systems of other nations; and furnishes essential services leading to accurate and uniform physical measurements throughout the Nation's scientific community, industry, and commerce. The Institute consists of a Center for Radiation Research, an Office of Measurement Services and the following divisions:

Applied Mathematics-Electricity-Heat-Mechanics-Optical Physics-Linac Radiation²—Nuclear Radiation²—Applied Radiation²—Quantum Electronics³-Electromagnetics3—Time and Frequency3—Laboratory Astrophysics3—Cryo-

genics3.

THE INSTITUTE FOR MATERIALS RESEARCH conducts materials research leading to improved methods of measurement, standards, and data on the properties of well-characterized materials needed by industry, commerce, educational institutions, and Government; provides advisory and research services to other Government agencies; and develops, produces, and distributes standard reference materials. The Institute consists of the Office of Standard Reference Materials and the following divisions:

Analytical Chemistry-Polymers-Metallurgy-Inorganic Materials-Reactor Radiation-Physical Chemistry.

THE INSTITUTE FOR APPLIED TECHNOLOGY provides technical services to promote the use of available technology and to facilitate technological innovation in industry and Government; cooperates with public and private organizations leading to the development of technological standards (including mandatory safety standards), codes and methods of test; and provides technical advice and services to Government agencies upon request. The Institute also monitors NBS engineering standards activities and provides liaison between NBS and national and international engineering standards bodies. The Institute consists of the following technical divisions and offices:

Engineering Standards Services-Weights and Measures-Flammable Fabrics-Invention and Innovation-Vehicle Systems Research-Product Evaluation Technology-Building Research-Electronic Technology-Technical Analysis-

Measurement Engineering.

THE CENTER FOR COMPUTER SCIENCES AND TECHNOLOGY conducts research and provides technical services designed to aid Government agencies in improving cost effectiveness in the conduct of their programs through the selection, acquisition, and effective utilization of automatic data processing equipment; and serves as the principal focus within the executive branch for the development of Federal standards for automatic data processing equipment, techniques, and computer languages. The Center consists of the following offices and divisions:

Information Processing Standards—Computer Information—Computer Services

-Systems Development-Information Processing Technology.

THE OFFICE FOR INFORMATION PROGRAMS promotes optimum dissemination and accessibility of scientific information generated within NBS and other agencies of the Federal Government; promotes the development of the National Standard Reference Data System and a system of information analysis centers dealing with the broader aspects of the National Measurement System; provides appropriate services to ensure that the NBS staff has optimum accessibility to the scientific information of the world, and directs the public information activities of the Bureau. The Office consists of the following organizational units:

Office of Standard Reference Data-Office of Technical Information and Publications-Library-Office of Public Information-Office of International

Relations.

Headquarters and Laboratories at Gaithersburg, Maryland, unless otherwise noted; mailing address Washington, D.C. 20234.
 Part of the Center for Radiation Research.
 Located at Boulder, Colorado 80302.

UNITED STATES DEPARTMENT OF COMMERCE • Maurice H. Stans, Secretary NATIONAL BUREAU OF STANDARDS • Lewis M. Branscomb, Director

Standard Reference Materials:

Calibration of NBS Secondary Standard Magnetic Tape (Computer Amplitude Reference) SRM 3200 Using the Reference Tape Amplitude Measurement "Process A" Model II

Sidney B. Geller

Information Processing Technology Division Center for Computer Sciences and Technology National Bureau of Standards Washington, D.C. 20234



National Bureau of Standards Special Publication 260-29

Nat. Bur. Stand. (U.S.), Spec. Publ. 260-29, 57 pages (June 1971) CODEN: XNBSA

Issued June 1971



Standard Reference Materials (SRM's) as defined by the National Bureau of Standards are "well-characterized materials, produced in quantity, that calibrate a measurement system to assure compatability of measurement in the nation." SRM's are widely used as primary standards in many diverse fields in science, industry, and technology, both within the United States and throughout the world. In many industries traceability of their quality control process to the national measurement system is carried out through the mechanism and use of SRM's. For many of the nation's scientists and technologists it is therefore of more than passing interest to know the details of the measurements made at NBS in arriving at the certified values of the SRM's produced. An NBS series of papers, of which this publication is a member, called the NBS Special Publication - 260 Series is reserved for this purpose.

This 260 Series is dedicated to the dissemination of information on all phases of the preparation, measurement, and certification of NBS-SRM's. In general, much more detail will be found in these papers than is generally allowed, or desirable, in scientific journal articles. This enables the user to assess the validity and accuracy of the measurement processes employed, to judge the statistical analysis, and to learn details of techniques and methods utilized for work entailing the greatest care and accuracy. It is also hoped that these papers will provide sufficient additional information not found on the certificate so that new applications in diverse fields not foreseen at the time the SRM was originally issued will be sought and found.

Inquiries concerning the technical content of this paper should be directed to the author(s). Other questions concerned with the availability, delivery, price, and so forth will receive prompt attention from:

Office of Standard Reference Materials National Bureau of Standards Washington, D.C. 20234

J. Paul Cali, Chief Office of Standard Reference Materials

OTHER NBS PUBLICATIONS IN THIS SERIES

- NBS Spec. Publ. 260, Catalog of Standard Reference Materials, July 1970. 75 cents.* (Supersedes NBS Misc. Publ. 260, January 1968 and NBS Misc. Publ. 241, March 1962.)
- NBS Misc. Publ. 260-1, Standard Reference Materials: Preparation of NBS White Cast Iron Spectrochemical Standards, June 1964. 30 cents.*
- NBS Misc. Publ. 260-2, Standard Reference Materials: Preparation of NBS Copper-Base Spectrochemical Standards, October 1964. 35 cents.*
- NBS Misc. Publ. 260-3, Standard Reference Materials:
 Metallographic Characterization of an NBS Spectrometric
 Low-Alloy Steel Standard, October 1964. 20 cents.*
- NBS Misc. Publ. 260-4, Standard Reference Materials: Sources of Information on Standard Reference Materials, February 1965. 20 cents.*
- NBS Misc. Publ. 260-5, Standard Reference Materials: Accuracy of Solution X-Ray Spectrometric Analysis of Copper-Base Alloys, March 1965. 25 cents.*
- NBS Misc. Publ. 260-6, Standard Reference Materials:
 Methods for the Chemical Analysis of White Cast Iron
 Standards, July 1965. 45 cents.*
- NBS Misc. Publ. 260-7, Standard Reference Materials: Methods for the Chemical Analysis of NBS Copper-Base Spectrochemical Standards, October 1965. 60 cents.*
- NBS Misc. Publ. 260-8, Standard Reference Materials: Analysis of Uranium Concentrates at the National Bureau of Standards, December 1965. 60 cents.*
- NBS Misc. Publ. 260-9, Standard Reference Materials: Half Lives of Materials Used in the Preparation of Standard Reference Materials of Nineteen Radioactive Nuclides Issued by the National Bureau of Standards, November 1965. 15 cents.*
- NBS Misc. Publ. 260-10, Standard Reference Materials: Homogeneity Characterization on NBS Spectrometric Standards II: Cartridge Brass and Low-Alloy Steel, December 1965. 30 cents.*

- NBS Misc. Publ. 260-11, Standard Reference Materials: Viscosity of a Standard Lead-Silica Glass, November 1966. 25 cents.*
- NBS Misc. Publ. 260-12, Standard Reference Materials: Homogeneity Characterization of NBS Spectrometric Standards III: White Cast Iron and Stainless Steel Powder Compact, September 1966. 20 cents.*
- NBS Misc. Publ. 260-13, Standard Reference Materials:
 Mössbauer Spectroscopy Standard for the Chemical Shift
 of Iron Compounds, July 1967. 40 cents.*
- NBS Misc. Publ. 260-14, Standard Reference Materials: Determination of Oxygen in Ferrous Materials --SRM 1090, 1091, and 1092, September 1966. 30 cents.*
- NBS Misc. Publ. 260-15, Standard Reference Materials:
 Recommended Method of Use of Standard Light-Sensitive
 Paper for Calibrating Carbon Arcs Used in Testing
 Textiles for Colorfastness to Light, June 1967.
 20 cents.*
- NBS Spec. Publ. 260-16, Standard Reference Materials:
 Homogeneity Characterization of NBS Spectrometric
 Standards IV: Preparation and Microprobe Characterization
 of W-20% Mo Alloy Fabricated by Powder Metallurgical
 Methods, January 1969. 35 cents.*
- NBS Spec. Publ. 260-17, Standard Reference Materials: Boric Acid; Isotopic and Assay Standard Reference Materials, February 1970. 65 cents.*
- NBS Spec. Publ. 260-18, Standard Reference Materials: Calibration of NBS Secondary Standard Magnetic Tape (Computer Amplitude Reference) Using the Reference Tape Amplitude Measurement "Process A", November 1969. 50 cents.*
- NBS Spec. Publ. 260-19, Standard Reference Materials: Analysis of Interlaboratory Measurements on the Vapor Pressure of Gold (Certification of Standard Reference Material 745), January 1970. 30 cents.*
- NBS Spec. Publ. 260-20, Standard'Reference Materials: Preparation and Analysis of Trace Element Glass Standards. (In preparation)
- NBS Spec. Publ. 260-21, Standard Reference Materials:
 Analysis of Interlaboratory Measurements on the Vapor
 Pressures of Cadmium and Silver, January 1971. 35 cents.*

- NBS Spec. Publ. 260-22, Standard Reference Materials: Homogeneity Characterization of Fe-3Si Alloy, February 1971. 35 cents.*
- NBS Spec. Publ. 260-23, Standard Reference Materials: Viscosity of a Standard Borosilicate Glass, December 1970. 25 cents.*
- NBS Spec. Publ. 260-24, Standard Reference Materials: Comparison of Redox Standards. (In preparation)
- NBS Spec. Publ. 260-25, Standard Reference Materials:
 A Standard Reference Material Containing Nominally Four
 Percent Austenite, February 1971. 30 cents.*
- NBS Spec. Publ. 260-26, Standard Reference Materials: National Bureau of Standards-U.S. Steel Corporation Joint Program for Determining Oxygen and Nitrogen in Steel, February 1971. 50 cents.*
- NBS Spec. Publ. 260-27, Standard Reference Materials: Uranium Isotopic Standard Reference Materials, April 1971. \$1.25.*
- NBS Spec. Publ. 260-28, Standard Reference Materials: Preparation and Evaluation of SRM's 481 and 482 Gold-Silver and Gold-Copper Alloys for Microanalysis. (In preparation)

^{*}Send order with remittance to: Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402. Remittance from foreign countries should include an additional one-fourth of the purchase price for postage.

TABLE OF CONTENTS

		PAC	žЕ
1.	Int	roduction	2
2.		ory of Operation of the NBS Measurement ystem (Model II)	4
	Α.	System Components	4
		1. Signal Amplitude Read Channel Components	4
		2. Write Channel Components	5
		3. Auxiliary Components and Systems	5
	В.	Description of System Operation	5
		1. Signal Amplitude Read Channel Operation	5
		2. Write Channel Operation	3
	С.	Switching System 10)
		1. Signal Amplitude Read System 10	Э
		2. Write System	1
3.		ibration and Operation of the Model II ystem	2
	Α.	Dc Calibration Procedures	5
	В.	Ac Calibration Procedures	5
	С.	Master Gain Calibration and Operation of the Model II System	7
		1. Output Voltage e (%) versus Write Current I Curves	3
		2. ABC Chart Measurements	9
		3. Candidate Tape Calibration Procedures . 22	1
		4. Additional System Checking and Calibrating Techniques	1

4.	Notes to Reference Tape Users					24
5.	Component List					28
6.	Acknowledgements	 •			•	33

LIST OF FIGURES

		PAGE
Figure	No.	
1.	NBS Model II Measurement System	34
2.	Signal Amplitude Read Channel Block Diagram	35
37.	Signal Amplitude Read Channel Circuit Diagrams	36-40
8.	Write Channel Block Diagrams	41
911.	Write Channel Circuit Diagrams	42-44
12.	Switching System for the Read Channel	45
13.	Switching System for the Write Channel	46
14.	Front Panel Layout for the Model II System.	47
15.	e _o (%) <i>versus</i> I _w Curve	48
16.	ABC Chart Recording	49

CALIBRATION OF NBS SECONDARY STANDARD MAGNETIC TAPE
(COMPUTER AMPLITUDE REFERENCE) SRM 3200
USING THE REFERENCE TAPE AMPLITUDE MEASUREMENT "PROCESS A"
MODEL IT

Sidney B. Geller

Information Processing Technology Division Center for Computer Sciences and Technology National Bureau of Standards Washington, D.C. 20234

This publication describes the design, operation and calibration of the NBS signal amplitude measuring system (Process A - Model II) that is used for calibrating unrecorded Secondary Standard Magnetic Tapes (Computer Amplitude Reference) SRM 3200. This system supercedes the measurement system that was described in the NBS Special Publication 260-18 (November 1969). The signal level calibration is made with respect to a reference signal level derived from the NBS Master Standard Magnetic Tape (Computer Amplitude Reference) that is kept in repository at NBS. The techniques for measuring and recording the data that accompany each Secondary Standard Magnetic Tape in the form of strip chart recordings and saturation curves are described.

Key words: Average signal peak level; computer amplitude reference; magnetic tape; master standard; saturation curves; secondary standard; signal level calibration; standard reference materials; unrecorded reference.

1. Introduction

The characteristics of present day magnetic computer tapes are the result of long term research and development by the magnetic tape industry. Technological developments in related fields and transducer-tape interplay have stimulated continuing improvement of the tape media and their performance. This has often led to differences in tape characteristics and to marginal operation when tapes are interchanged between systems. The only tapes previously available for quality assurance purposes have been industry supplied standards.

At the request of industrial users of computer tape, Government procurement agencies, producers of magnetic computer tapes, and producers of tape handling equipment the National Bureau of Standards has developed a tape measurement system and is supplying unrecorded Secondary Standard Magnetic Tapes (Computer Amplitude Reference) through the NBS Office of Standard Reference Materials.

This material, which is designated as the NBS Standard Reference Material No. 3200 (SRM 3200), consists of a 600-foot or greater length of secondary reference tape accompanied by applicable test and calibration data, and a description of the equipment and procedures employed for measurement of the tape. At least 600 continuous feet on each tape must meet all of the requirements that are described on the accompanying SRM 3200 certificate. The remaining tape footage will also be calibrated but may or may not meet the certificate requirements. The calibration data charts will physically locate the 600 foot region of interest on each reel. The secondary tapes are 1/2 inch wide unrecorded magnetic computer tapes wound on 8-1/2 inch diameter precision reels.

Each SRM 3200 is calibrated in terms of a 100% signal level that is derived from the NBS Master Standard Magnetic

Tape (Computer Amplitude Reference) which is kept in repository at NBS. This signal level calibration is done at recording densities of 200, 800, 1600 and 3200 flux reversals per inch. Information in the form of signal output strip charts accompanies each secondary tape. These are recorded on the first read-while-write pass from 3 head tracks; one near each tape edge and one at the tape center and are referred to as ABC charts. A set of X-Y recorder curves relating the reproduce head output voltage to the write current on the first read-while-write pass at each bit density of both the NBS master and each secondary tape also accompanies the SRM 3200. These are referred to as e (%) versus $I_{\rm W}$ curves or X-Y curves.

Presently, the main criteria for the selection of unrecorded amplitude reference tapes for calibration as secondaries are signal amplitude uniformity and proximity of read-while-write output voltage to that of the master. The instantaneous track-to-track variation in the average signal peak amplitude is limited to a maximum of 3% among the outputs from the NBS test tracks 2, 5 and 8. The location of these tracks is defined in USASI Document X3.22-1967. The maximum variation in the longitudinal average signal peak amplitude along each test track is limited to 4% over the documented 600 foot length of tape. The value of the average signal peak amplitude measured from each test track is within 10% of the signal level derived from the NBS Master Standard Magnetic Tape (Computer Amplitude Reference.) These criteria are applied for peak signal recording on degaussed (fully ac erased) tape when measured on the NBS system in the manner described in this publication.

Theory of Operation of the NBS Measurement System (Model II)

A. System Components

Figure 1 shows the organization of the Model II system used for measuring and calibrating the unrecorded NBS Secondary Standard Magnetic Tapes (Computer Amplitude Reference) SRM 3200. The system consists of a write channel (NRZI mode), three identical signal amplitude read channels (Channels A, B and C), a supply voltage section that includes a precision voltage dividing network and a switching system for use in both the operation and the calibration of the system. Various readout instruments are also included in the system.

The following descriptive material lists the components that appear in each of the sections or channels. One of the figures that is given with each channel contains the block diagram of the channel functions and the other figures consist of the circuit realizations of the block functions. Note that within most of the individual blocks a figure number is inscribed which identifies the circuit diagram that corresponds to that block.

- Signal Amplitude Read Channel Components (figures 2-7)
 - a. A slotted read-write head (IBM Assembly No. 5417960, Part No. 2510730 or equivalent), a line driver LD-1, a termination network TE-1B, and attenuator circuit AT-1 and a wideband preamplifier WPR-1 with internal and external gain potentiometers $\rm R_3$ and $\rm R_4$ and amplifier OA-1.
 - b. A peak level detect-sample-and-hold circuit PD-SH-1 that contains comparator IC-1, transistors ${\rm T}_6$ through ${\rm T}_{14}$, and diodes ${\rm D}_1$ through ${\rm D}_{\rm h}$.

- c. Level shifting, range setting and summing circuits containing operational amplifiers OA-2 through OA-5.
- d. External 10-turn potentiometers R_5 for setting the "MASTER GAIN" of the system.
- e. A passive R-C signal peak averaging circuit.
- 2. Write Channel Components (figures 8-11)
 - a. A variable frequency square wave generator G-1 whose frequency ranges from at least 22.5 kHz to 360.0 kHz, a pulse counter, a binary counter circuit BC-1 and pulse level shifting circuits LS-1.
 - b. A slotted read-write head (IBM Assembly No. 5417960, Part No. 2510730 or equivalent), a write head current driver circuit WD-1 and a motorized write current amplitude control circuit CC-1.
- 3. Auxiliary Components and Systems
 - a. Four precision voltage sources (±6.0, ±14.0, ±14.0, +30.0 volts) and a dividing network DV-1 for providing dc calibration voltages. Operational amplifiers OA-6 and OA-7. One precision digital voltage source.
 - b. A function switching system containing 9 wafer switch assemblies, 2 pushbutton switches, 1 lever and 1 toggle switch (figures 12-13).
 - c. A modified IBM-2401-VI Tape Transport.
 - d. Read-out devices: a 6-track ABC chart recorder, an X-Y recorder, a digital panel meter DPM-1 and a digital voltmeter DVM-1.
- B. Description of the System Operation
 - 1. Signal Amplitude Read Channel Operation (figures 2-7)

The signal amplitude measurements are performed at all bit densities on candidate tapes that

have been initially degaussed and then recorded with all "ones" in the NRZI mode.

- The signal which has been reproduced by a read-while-write operation from a candidate tape is passed through a unity gain, line driving amplifier LD-1 which is physically located at the read head. The line is terminated by TE-1B and network AT-1. AT-1 attenuates the incoming signals so that the inputs to the WPR-1 preamplifiers will fall within a reduced range of amplitudes for the different recording densities. AT-1 is adjusted with R_1 and R_2 . Typical values of output signal from LD-1 have been found to lie in the range of 12.0-14.0 mV p/p at 3200 frpi and 17.0-22.0 mV p/p between the densities of 1600 to 200 frpi. The WPR-1's are adjusted with R2 to operate at gains of 470 with R_{j_1} set at its mid-value of 500 ohms.
- b. The amplified signals from the WPR-1's are then fed into the peak-detect-sample-andhold PD-SH-1 circuits via OA-1. PD-SH-1 converts the ac signals into dc levels that are equal to their peak values. 3.000 volts dc represents the 100% level for the measuring system and all output levels are described in terms of their value as a percentage of 3.000 volts.

The peak detect-sample-and-hold circuit PD-SH-1 in figure 5 operates as follows:

The hold capacitor C_1 is charged to the positive signal peak value through diode D_1 . Simultaneously, the output signal from OA-1 is fed into the high-speed comparator inte-

grated circuit IC-1. The output from IC-1 is a 4.0 volt p/p pulse train whose widths are determined by the zero cross-over points of the signal. This pulse train is fed into the two network branches that are tied to the output of IC-1 at terminal 7. The pulses are integrated by capacitor C2 before driving the upper gating circuits consisting of T6, T7 and T_8 . This integration stretches the signal peak voltage hold time across C_1 , and therefore produces a sampling time margin. The sampling is initiated when the IC-1 output pulse signal level falls from +4.0 volts towards ground and is differentiated at the input to T_{11} . The differentiated signal triggers the T_{12} - \mathbf{T}_{13} current switching circuit and a strobe pulse is generated by T_{13} which drives the gate terminal of T_{11} (FET) during the stretched signal level interval. A dc level now appears across C2 and is held there until another strobe pulse is initiated by the next signal cycle.

- c. The input circuit of OA-2 is adjusted by $\rm R_9$ and $\rm R_{10}$ so that the dc levels from PD-SH-1 will track the incoming signal peak values.
- d. The output signal from C_2 is then fed into OA-3. The output from OA-3 is injected into the "MASTER GAIN" or "MG" branch of the final summing amplifier OA-4. The MG potentiometer R_5 is the principal calibration device of the system. The signal is offset by the OA-4 "% RANGE" branch voltage in order to attain the desired ABC chart percentage values. The output signal from OA-4 then is passed to the ABC and X-Y recording devices.

- e. A passive R-C averaging circuit with a time constant of R_A C_A = 0.30 seconds is used to average the output signal from each OA-4. As seen in figure 6, R_A = 100K Ω and C_A = 3.0 μ fd. The voltage across the capacitor C_A is applied to the ABC chart recorder track that is adjacent to the signal peak track that it is averaging. The upper track of each pair on the ABC chart is the average signal peak track. (See figure 16)
- 2. Write Channel Operation (figures 8-11)

The NBS signal amplitude read channel operates independently of the system from which the head-tape signal is derived, however the NBS write channel is designed to operate specifically with the IBM 2401-VI transport. This channel is not shown in detail because many different transports will be used with the SRM 3200 tapes in the field. Only the current control circuit CC-1, the binary counter circuit BC-1, the level shifter LS-1 and a simplified version of the write driver circuit WD-1 are shown (figures 9-11). WD-1 and the current source for WD-1 are both on the IBM 2401-VI "FHW" card. Additional level shifting beyond LS-1 is supplied by the "EPY" and "FAN" cards.

The following steps were taken to convert the IBM 2401-VI tape transport for continuous current and frequency control by the NBS system. These steps should be applied to any system for which similar control is desired:

a. Disable the internal bit rate generator and connect an external generator G-1. The pulse frequencies that are supplied by G-1 are as follows: 200 frpi - 22.5 kHz; 800 frpi -

- 90.0 kHz; 1600 frpi 180.0 kHz; and 3200 frpi 360.0 kHz.
- Since these frequencies produce double the desired bit rate they are used to trigger
 BC-1 which (1) halves the bit rate and (2) produces a constant amplitude square wave.
- c. The signal levels from BC-1 are then made compatible for driving the write head with level shifting circuits such as LS-1.
- d. Disable any step write current circuit if one exists.
- e. Disable or alter any circuits that are necessary in order to make it possible to record all "ones" in the NRZI mode.
- f. The current control circuit CC-l consisting of T_{22} , T_{23} , and T_{24} (figure 11) is used to control the output from a continuously variable current source circuit over a range of 0.0 to 50.0 mA dc of write head current. The total write head current is controlled with the potentiometer R_{15} . R_{15} is operated in the "MANUAL" mode (in conjunction with vernier control R_{16}) when the ABC chart recordings are made and in the "AUTOMATIC" mode when producing the X-Y curves. R_{15} is motor driven through one turn in 10 seconds during automatic operation. The head current I_w is measured and displayed with the digital panel meter DPM-1.

Any existent circuits that impede the current source from attaining its full range of values should be disabled or removed.

g. T_{25} and T_{26} form a constant current switch with matched circuit components so that equal values of write current will flow through each

winding of the write head during each half of the operating cycle. The switched head current is equal to the output from the current source and the switching rate is controlled by the level shifted pulse train that is applied to the base of T_{25} . The direction of current in the write head depends upon the instantaneous "on" and "off" states of T_{25} and T_{26} .

C. Switching System (figures 12-14)

The NBS Model II measuring system has a switching network that permits rapid dc, ac and "MASTER GAIN" calibration. However, these procedures could be performed with patch-cords or any other device that allows the user to cut into the circuitry.

The NBS measuring system contains 11 switches in the signal amplitude read section and 2 switches in the write section. The switches are shown in the simplified switching diagrams of figures 12 and 13. They are shown in their actual panel positions on the NBS Model II unit in figure 14. Figure 12 shows only the required switching sections for a single read channel. The other two read channels are controlled in an identical fashion by additional wafer sections that are stacked onto and are mechanically coupled to the same switch assemblies. The functions of the individual switches will now be described. Switch markings on the panel are in quotation marks:

- Switch S2: (Sections A, B, C): "OPERATE, SET CHART,

 AC CALIBRATE." Main function switch for
 the signal amplitude read channels.

- Switch S3: "Set X-Y." Pushbutton switch. Sets the 100% reference level on the X-Y recorder when depressed and the 0% level when released. The 100% level is equal to 5.000 volts dc.
- Switch S4: (Sections A to E): "ABC X-Y." Chooses the measuring mode and the output recording device.
- Switch S5: "OPERATE, EXTERNAL INPUT, DC CALIBRATE."

 External high level signals or dc calibration volts can be injected into the system under the control of S5.
- Switch S6: "2-3-4-5": Routes "DC CALIBRATE" volts to S5 from DV-1.
- Switch S7: "OP, %, AC, MG: (Not shown in detail in figure 12.) S7 is used to both open and/or to cut into the individual inputs of OA-4 for calibration and system check purposes.
- Switches S8
 - and S9: These switches are used for metering purposes only. All supply voltages and the outputs from OA-3 and OA-4 are measured by a digital voltmeter (DVM-1) via S8 and S9.
- Switch S10A: "GROUND T_{13C}" Toggle switch on circuit card.
 Used during "DC CALIBRATE".
- Switch S10B: "GROUND DVM". Pushbutton switch. This is used to check the DVM or oscilloscope ground level.
 - 2. Write System (See figure 13)
- Switch Sll: "OFF, LOCAL, MAIN FRAME." Main write current control switch. Reduces write current to zero in "OFF" or gives control of the write current to the NBS measurement system in "LOCAL". Sll can also be wired to return

current control to the transport main frame if desired.

Switch S12: "AUTO-MANUAL." Lever Switch. Chooses the mode of write current control. The automatic mode is used for X-Y recording and the manual mode is used for setting the reference current level for ABC charts. S12 also controls the X-Y recorder pen drop circuit and activates the potentiometer motor during X-Y recording. Note that there are 4 SPDT sections on S12. The normally open sets of points are designated by "N.O."

- 3. Calibration and Operation of the Model II System
 The calibration and operation of the read system is
 accomplished in the following sequence:
 - A. Dc Calibration
 - B. Ac Calibration
 - C. "MASTER GAIN" Calibration and System Operation.

The calibration of the Model II system proceeds from the output of OA-4 back toward the input circuitry. The first adjustments are made on the output summing amplifier OA-4 which has the following input lines: (See figure 6)

- a. "MASTER GAIN" (MG) R5
- b. "AC CALIBRATE" (AC) R₆
- c. "SET CHART" (SC) R7
- d. "% RANGE" (%) R₈

 $\rm R_6$, $\rm R_7$, and $\rm R_8$ are adjusted so that the gain of OA-4 relative to dc inputs on these lines is equal to G = 1.667. This gain converts the input signal amplitudes to output values that yield a direct relationship between the chart divisions and the percentage value of the signal under test.

The functions of these ${\sf OA-4}$ inputs and adjustments are as follows:

- a. The "MASTER GAIN" potentiometer $\rm R_5$ adjustment sets the final gain of each read channel so that it will produce the desired reference output level as provided by the NBS master tape. The NBS secondary standard magnetic tapes are then calibrated with respect to this level. The "MG" input branch to OA-4 is functional during the normal "OPERATE" (S2) mode.
- b. The "AC CALIBRATE" input to OA-4 is used in the "AC CALIBRATE" (S2) mode of operation. This mode uses a simulating ac signal to test the stability and adjustment of the system.
- c. The "SET CHART" input to OA-4 is used in the "SET CHART" (S2) mode of operation. In this mode 3.000 volts dc is injected into OA-4 and produces the output voltage level which is used to set the X-Y and ABC recording devices into their 100% reference states prior to recording.
- d. The "%" input to OA-4 affects each of the preceding modes by providing a controlled offset voltage. This offset voltage is adjusted with the calibrated 10 turn potentiometer R₁₂ so that the signal output from OA-4 will consist of a desired percentage of the total signal range. For example, a range consisting of from 75% to 125% of the total signal amplitude is charted on a strip chart recorder by offsetting the lower 75% of the output signal and then selecting that chart recorder range that will encompass the next 50% of the total signal level over its limits.

An NBS ABC chart recorder track has a useful width of 10 major linear divisions as shown in figure 16. When the recorder sensitivity is set to 250mV/div then full chart deflection is obtained with 2.500 volts dc. If the chart centerline is chosen as the 100% reference level then 1.250 volts dc output from OA-4 is equal to 100%. Since 3.000 volts dc into OA-4 represents the 100% level for the system, it is necessary to offset this by inserting 2.250 volts dc onto the "%" line. This results in an OA-4 output equal to 0.750 volts times the OA-4 gain of G = 1.667 or 1.250 volts during the "SET CHART" (S2) mode of operation. The bottom of the chart represents the 75% signal level and the top of the chart represents the 125% signal level. The NBS system is designed so that the lowest percentage values on the 250 mV/div chart can be calculated from:

Lowest %= $\frac{"\% \text{ RANGE" input voltage x 100}}{3.00}$

On the 250 mV/div scale setting the highest chart percentage is 50% above this lowest value.

NOTE: This same "%" offset capability can be used to compare relative signal peak values and to measure the distribution of incoming signal peaks on a high sensitivity range of an oscilloscope. This measurement, however, does not require prior peak detection and sample-and-holding of the signal, i.e., the signal is passed directly from WPR-1 to OA-4. When the oscilloscope sweep rate is set to display only one half or less (positive or negative) of one signal cycle per trace then a broad arched band of light appears on the screen. The broadness of the band is a function of the scope sensitivity and of the distribution of the signal peak amplitudes read from the tape. The intensity of the

light band varies across its height with the brightest level appearing at the amplitude related to the most prevalent signal peak value.

- A. Dc Calibration Procedures (figures 4 to 6, 12)
 - 1. The "AC", "SC" and "%" inputs of the OA-4's in figure 6 are set for gains of G=1.667 by injecting 3.000 volts dc from the precision digital voltage source into each of these inputs via switch S7 and adjusting trimmers R_6 , R_7 , and R_8 for an output of 5.000 volts dc from OA-4 as measured on DVM-1. This can be done on an individual basis via S7 with all inputs held at zero volts except for the one being adjusted.
 - 2. After the OA-4 inputs have been adjusted then the peak detect sample-and-hold PD-SH-1 system is dc calibrated as follows:
 - a. Open the input to OA-1 at point A of R $_4$ (via S $_5$) and set R $_4$ to its mid-point value of 500 Ω . R $_4$ is an external 10 turn potentiometer with a calibrated dial. (figure 4)
 - b. Short the collector of T_{13} to ground (via S10A in figure 5).
 - c. Inject 2.000, 3.000, 4.000 and 5.000 volts dc sequentially into R_{μ} from the precision voltage divider source DV-1 (figure 7). This is done with switch S5 and S6.
 - d. Adjust R_9 and R_{10} at the OA-2 inputs (figure 6) until the dc outputs from OA-3 track these voltages within an accuracy of at least 0.25%. This completes the dc calibration and all switches or connections are returned to normal.
- B. Ac Calibration Procedures (figures 3, 4)
 - 1. This is accomplished in two steps when the system is ac calibrated for the first time after the dc calibration has been completed:

Step (1) - An external sine wave signal is shunted around AT-1 and is injected directly into the connector to the input capacitors of each of the WPR-1 preamplifiers with S2 in "AC CAL" (figure 3). It has been found that an input signal amplitude of 12.7 mV p/p is a good value to use as the nominal operating signal level. The internal WPR-1 gain trimmers R3 are then adjusted in each of the 3 read channels so that the output from each OA-3 is equal to 3.000 volts dc. This corresponds to an output of 6.0 volts peak to peak from WPR-1. The frequencies of the injected signals are 180 kHz, 90 kHz, 45 kHz, and 11.25 kHz for 3200, 1600, 800 and 200 frpi, respectively.

Step (2) - After each WPR-1 has been set for an equal gain of 470 the external sine wave signal is then injected into the input of attenuator AT-1 at point A (figure 3) with S2 in "OPERATE". For 3200 frpi the input signal level is set to 14.2 mV peak to peak at 180 kHz and the trimmer R₁ is adjusted so that the output from OA-3 is again 3.000 volts dc. The input signal is then set to 22.5 mV p/p at 45 kHz and the trimmer Ro is set so that the output from OA-3 is again 3.000 volts dc. Trimmers R, and R, are now permanently secured and never readjusted. In operation switch S1 (figure 3) is used to activate the R1 trimmer circuit at 3200 frpi and the R, trimmer circuit at 1600 to 200 frpi

so that the WPR-1's will be able to operate over a reduced range of gains for all densities. The ac calibration is now completed and if desired only step (2) need be performed for checking the dynamic response of each of the three read channels and the output recorders.

C. "MASTER GAIN" (MG) Calibration and Operation of the Model II System

After the dc and ac calibrations are completed the system is ready for its final working adjustment using either the NBS master or a working reference tape. This step is accomplished at each density by running either one of these reference tapes and adjusting the three external MG potentiometers R_{5} . The sequence of operations are as follows:

- 1. Produce an uncalibrated ${\rm e_o}$ (%) versus ${\rm I_w}$ curve using the master or working reference tape and determine the reference write current level at the initial signal peak.
- 2. Produce an ABC strip chart recording of the signal outputs from 3 head tracks using the reference write current level. Adjust the MG potentiometers to achieve the correct percentage values on the ABC chart as determined by the master or working reference tape.
- 3. Now produce the calibrated $\mathbf{e}_{_{\bigcirc}}$ (%) versus $\mathbf{I}_{_{\mathbf{W}}}$ curves and ABC charts for the NBS master tape and for each candidate tape.
- 4. Record the MG numbers or voltages and make a "master template". Each one of these operations must be repeated for each of the 4 bit densities. The following is a detailed description of steps 1 to 4:

- 1. Output Voltage e_0 (%) versus Write Current I_W Curves (figure 15)
 - (a) In order to determine the reference write current levels at which the ABC strip charts for the candidate tape are to be produced, it is first necessary to make an e (%) versus I curve for the master tape or a working reference tape at each operating density. This reference level is the "initial" saturation write current and is defined as the minimum write current level that produces the maximum value of output read head voltage as plotted on the X-Y chart. The output voltage e (%) is always obtained during a read-while-write pass on a previously bulk erased tape. The e (%) versus I curves are measured from the output of the center track (track #5) of the 9-track read head and are produced over a section of tape which lies approximately 100'feet past the beginning mark of the calibrated 600 foot section of the reference
 - (b) The e_O (%) versus I_W curves are plotted on an X-Y recorder whose X axis is driven by a voltage that is derived from the voltage drop across the 10 ohm resistor in series with the center tap of the write head (figure 11). These voltage drops are converted by an X axis gain adjustment into chart abscissae values that represent the write head current in milliamperes. The range of the write current in the system is continuously controlled from 0 to 50.0 mA by CC-1 and the motorized potentiometer unit R₁₅. The write current is read from DPM-1.
 - (c) The Y axis of the X-Y recorder is driven directly by the output signal voltage from OA-4. The Y axis gain is calibrated so that 5.000 volts dc will

drive the recorder pen to the line that has been chosen as the 100% level on the e_0 (%) versus I_W chart. These 5.000 volts dc are derived from OA-4 in the "SET CHART" (S2) - "X-Y") (S4) mode of operation by depressing pushbutton S3.

- (d) The operating procedure is as follows:
 - (1) The NBS master or working reference tape is threaded onto the tape transport.
 - (2) The system is switched into "OPERATE" (S2)
 "X-Y" (S4).
 - (3) The current control switch Sll is placed into "LOCAL".
 - (4) S12 is depressed into "AUTO" and the tape transport is started.
 - (5) The motorized potentiometer R_{15} varies the write current from zero to 50.0 mA and the e_0 (%) versus I_w curve is plotted.
 - (6) During step (5) the external "MASTER GAIN" potentiometer for the center channel (channel B-track #5) is adjusted to bring the e₀ (%) signal peak value to within 5% of the 100% X-Y chart level that was set in step (c) above. This may require several passes over the same chart as the tape is running.
- 2. ABC Chart Measurements (See figure 16)

These measurements are made after the initial saturation write current level has been determined from the e_ (%) versus \mathbf{I}_{w} chart as follows:

(a) The system is switched into the "ABC" (S4) - "SET CHART" (S2) mode of operation and the ABC strip chart recorder tracks are adjusted or "set" to their 100% level. For example, the chart centerline is used as the 100% level if the "% RANGE" voltage is set equal to 2.250 volts dc with R₁₂ and the recorder sensitivity set to 250 mV/div.

- (b) After the ABC chart is "set", the write head current is adjusted to the initial saturation current level previously determined using the CC-1 write current control potentiometers R₁₅ and R₁₆ with S12 in the "MANUAL" position. The system is then switched into the "ABC" (S4) "OPERATE" (S2) mode of operation and the ABC chart recorder and tape transport are activated.
- (c) (l) The ABC chart speed is set at 1 mm/s.
 - (2) The IBM 2401 VI tape transport speed is 112.5 in/s.
 - (3) Each major horizontal chart division (5 mm) represents the passage of 47 feet of tape.
 - (4) The 6 ABC tracks consist alternately of the signal peak outputs and the average of these signal peak outputs as derived from 3 head tracks (tracks #2, #5 and #8).
- (d) If the NBS master tape is being run on the transport, then the three external "MASTER GAIN" potentiometers R_5 are adjusted so that the signals on all of the ABC chart recorder tracks fall exactly at the pre-set 100% level. If a working reference tape is used instead of the master tape, then each MG potentiometer R_5 is set so that the signal level on each ABC track will fall at the predetermined relative percentage values for the working tape outputs. For example, for a particular working tape the MG potentiometers R_5 may have to be set to produce: track A = 98% level, track B = 95% level and track C = 97% level relative to the 100% master tape level. The system is now completely calibrated.

- 3. Candidate Tape Calibration Procedures
 - (a) When the "MASTER GAIN" potentiometers have been adjusted as described above then calibrated e $_{\rm O}$ (%) versus I $_{\rm W}$ curves are produced for all of the candidate tapes and the master tape by repeating the procedures in Section 3, C, 1, d, but omitting step 6 in this section.
 - (b) The reference current values that will now be used to produce the final ABC charts are marked on each of the calibrated X-Y curves that accompany the SRM 3200's as shown in figure 15. An ${\rm e_0}$ (%) versus ${\rm I_W}$ chart that was derived from the NBS master tape will also be marked and included in the package.

Since the system is completely calibrated the peak output voltage ${\rm e_o}$ (%) from the NBS master tape at each recording density will now fall at the 100% level on its X-Y chart and the peak voltage outputs from the candidate secondary tapes will appear directly in terms of their relative percentage values to the master tape. For example, if the peak output voltage ${\rm e_o}$ (%) for an NBS candidate secondary tape is reached at the 98% chart level, then that tape has been measured on the NBS calibration system as having a peak output voltage that is 2% less than the peak output voltage derived from the NBS master tape.

- (c) The steps in Section 3, C, 2, a, through 3, C, 2, c, are now repeated for all candidate secondary reference tapes at each bit density. These procedures will result in calibrated ABC charts for these tapes. The candidates are now completely calibrated.
- 4. Additional System Checking and Calibrating Techniques
 Techniques have been developed for checking and calibrating the NBS Model II measurement system which do not

require the constant use of a working reference tape. In each instance the method assures that the overall system gain and the MG potentiometers ${\bf R}_5$ are maintaining their original values.

- (a) "MASTER GAIN" Numbers and Voltages The "MASTER GAIN" potentiometers R₅ are 10-turn units with calibrated dials. After completing Section 3, C, 2, d, the numbers on these MG dials are recorded and can serve as future references. That is, if the system is dc and ac calibrated and the MG potentiometers R5 are reset to these same dial numbers then the system is back in its original operating condition. These MG numbers are related only to the particular head that was used when they were derived. A more precise technique for resetting the MG potentiometers to their original values is achieved in the NBS system by injecting 3.000 volts dc into the calibrated "MG" inputs of the OA-4's with all of the other inputs at zero (switch S7 in "MG"). The output voltage from the OA-4's are then logged and the MG potentiometers can then be reset very precisely to these OA-4 output voltages when desired. This approach eliminates the effects of mechanical dial errors in the MG number method.
- (b) Master Template Technique:
 An alternate technique for testing the stability of the entire NBS measurement system as well as for recalibrating the system without the use of a reference tape is with a "master template".
 This template is produced as an ABC 6-track chart recording immediately after the system has been calibrated (after Section 3, C, 2, d). It is done by disconnecting the LD-1 line driver outputs and producing the ABC chart by injecting a sine wave

signal into the input of the calibrated system at AT-1. The frequencies and amplitudes of these signals are the same as those discussed in the Section 3. B. For example, at 3200 frpi a 180 kHz, 14.2 mV p/p signal is injected into AT-1. Since the injected sine wave signal consists of constant amplitude peaks the master template will consist of smooth lines at a fixed level on each ABC track. This template includes the effects of the entire measuring system on the injected signal. During an actual tape calibration run the system can be rechecked regularly by producing new ABC charts using the same injected sine wave signal and comparing the levels on the new charts to the levels on the original master templates. If necessary, amplifier gains can be adjusted with Ro or R, to bring these levels into line with the master levels. A separate template is produced at each bit density for each calibrating head and the set of templates is stored with that head when it is removed from service.

When the response of the measuring system is recorded in this fashion, it is possible to observe changes in the head-tape output signal with time. These changes are due to variations in environmental and operating conditions as well as to the mutual physical effects of the heads and tapes on each other.

(c) Ac Calibration Mode:

This mode of calibration is similar to the master template mode with the exception that the reference sine wave signal is switched via S2 directly into the WPR-1's and the OA-4 input trimmers R_6 ("AC CAL") are set so that the 6-track chart recordings all fall at the 100% level in response to these

signals. The MG adjustment is assumed to be correct and no template is required. This mode offers a rapid system check during a candidate tape calibration run but is not as complete as the master template method. The sine wave generator can be permanently connected into an "AC CAL" input jack and the line drivers do not have to be disconnected in this mode.

- 4. Notes to Reference Tape Users
 - A. Important: The NBS Secondary Standard Magnetic Tapes (Computer Amplitude Reference) SRM 3200 should be used sparingly so as to minimize physical changes to the tape and to assure continued performances as near to the supplied calibrations as possible.

It has been found that the best correlation with the NBS measurement system results can be produced under the following conditions:

- (1) The tape is bulk ac erased before writing.
- (2) The dc erase head on the tape transport is not energized during the measurement process.
- (3) A slotted read-write head (IBM Assembly No. 5417960 Part No. 2510730 or equivalent) is used as the transducer.
- (4) The curves are made during a first read-while-write pass.
- (5) The characteristics of the tape transport such as speed, tension and guidance should be similar to the IBM 2401-VI.

Departure from one or more of these conditions can result in variations from the calibrated results.

B. The NBS Secondary Standard Magnetic Tape (Computer Amplitude Reference) SRM 3200 is packaged in lengths of approximately 900 to 1200 feet of tape per reel.

At least 600 continuous feet of tape within this length satisfy the requirements that are stated on the accompanying certificate. However, the full reel can be used for adjustment purposes because calibration data for the entire length of tape are included on the ABC charts. Originally the SRM 3200's were packaged in exact 600 foot lengths. The decision to change to the 900 to 1200 foot format resulted from experimental evidence which indicated that the longer tape lengths reduced the signal "rise" effect. It has been noted that many different tapes display a rise in signal amplitude as the tape is read from end to end, with the signal increasing most rapidly as the reel hub is approached. It is believed that the increase in signal amplitude is caused by effects of the pressure variation per unit length of tape upon the tape surface after it has been wound and stored. The longer tape length lowers this pressure gradient and the percentage signal amplitude variation over any continuous length of tape is also reduced.

Figure 16 shows 2 out of 3 channels on a typical ABC chart recording with the principal 600 foot section lying between the two right hand "marks". The length of tape between the "Beginning of Tape" (BOT) marker to the 600 foot starting "mark" is also shown on each ABC chart. The time in seconds that is required to reach this starting "mark" from the BOT mark is found from:

Time (in seconds)= $\frac{\text{length from BOT to starting "mark" (feet)}}{\text{speed of transport (feet/second)}}$

Note that the length of tape between each horizontal ABC chart division is approximately 47 feet, therefore in figure 16 the distance from the BOT mark to the starting "mark" is 376 feet. As an example, if the transport speed is 112.5 inches per second (9.38 ft/s) then the time required to reach the starting "mark" from the BOT marker is

$$T = \frac{376 \text{ feet}}{9.38 \text{ ft/s}} \simeq 40 \text{ seconds}$$

It is anticipated that SRM 3200 users will devise other means for finding the starting "mark" after it has been located by them for the first time. For example, additional BOT and EOT ("End of Tape") markers may be added to the tape according to the operational design of each particular system. However, cutting the tape to different lengths is not recommended since it will alter the signal rise characteristics.

e (%) versus I saturation curves for 3200, 1600, 800 and 200 frpi will accompany the NBS Secondary Standard Magnetic Tape (Computer Amplitude Reference) SRM 3200 from which they are derived. In addition, the four e (%) versus I saturation curves that were obtained from the NBS Master Standard Magnetic Tape (Computer Amplitude Reference) at these bit densities will also be included in the package. The user will therefore be able to use these curves in order to determine the relationships at different write current levels between the NBS master tape and the NBS secondary tapes. The user should note that every e (%) value on the NBS master tape X-Y curve can be assumed to be the 100% reference level and that the secondary tape outputs are then considered in

terms of their percentage relationship to these master levels at whatever write current has been chosen. NBS has chosen the initial saturation current at the \mathbf{e}_0 (%) peak as the basic reference current level at which all of the ABC charts are produced. This level is marked on the X-Y curves as shown in figure 15. The ABC chart shown in figure 16 was produced at the current level that was marked for the tape T-1 in figure 15.

It has been found at 3200 frpi that most initial saturation write current levels lie between 13.0 to 16.0 mA and that between 200 and 1600 frpi most values lie between 26.0 to 30.0 mA. These results were obtained with a number of IBM slotted read-write heads described in Section 2, A, 1, a, and with groups of various industry tapes chosen at random.

- D. ABC strip charts derived from 3 head tracks at each of the 4 bit densities accompany the NBS secondary tapes from which they were derived. Data from each read head are recorded on two adjacent pen tracks with the signal peak amplitude appearing on the lower track and the average peak amplitude of the signal appearing on the upper pen track. Figure 16 shows tracks B, B, C and C as they appear on a typical ABC strip chart recording. The bar over the track letter indicates the average peak value track.
 - (1) Chart track A corresponds to the signal output from head track No. 2.
 - (2) Chart track B corresponds to the signal output from head track No. 5.
 - (3) Chart track C corresponds to the signal output from head track No. 8.

 The head tracks are numbered in accordance

with USA Standard Recorded Magnetic Tape for Information Interchange (800 CPI, NRZI) - USASI X3.22-1967.

E. Construction Notes

- (1) Printed circuit layout figures for the plug-in cards that are used in the NBS Model II system will be made available upon request.
- (2) The muffin fans are important for maintaining the dc stability of the solid state devices and should be used. They are positioned to move the air through the side of the SDS card cage. The NBS laboratory is maintained at a temperature of 70° ± 1° F.
- (3) Separate ± 14.0 volt supplies are used for the low signal level circuits in WPR-1 and for the high level signal circuits in PD-SH-1.
- (4) Coaxial leads are used in the low signal level input circuits and switches.
- (5) The NBS system is designed so that all printed circuit card adjustments are available from the front of the machine. This includes all internal trimmer resistors.
- (6) If the NBS circuit cards and the SDS Type MT-12 card cages are used it will be necessary to cut open the common pin No. 51 buss line on the SDS cage etched circuit plate.
- (7) The three read channels A, B and C do not interact, therefore, it is feasible to build a single channel read system if desired. Also, if only ABC charts are desired then it is not necessary to build the NBS write control system.

5. Component List

The mention of specific equipments or components in any portion of publication is not to be construed as an endorsement of these items by NBS to the exclusion of other equiv-

alent devices. There is considerable latitude in the choice of semi-conductor components, potentiometers, recording, reproducing and measuring devices. The following is a tabulation of the devices that are used in the NBS measurement system Model II.

Note: The marking of a component or heading with an asterisk indicates that only one each of these components or devices under the heading is used in the entire system. All other components unless otherwise indicated are used one each per channel, therefore, three of each are used in this system.

Transistors	T(Numbers in Figures)	Type			
2N3646	7-10, (17-22)* 27, 28	NPN Switching			
2N3638	6, 11, 12, 13, 15*, 16*	PNP Switching			
2N916	1-3	NPN High Frequency Amplifier			
2N3831	4, 5, 25, 26	NPN High Speed Switch			
2N1700	23*, 24*	NPN Switching			
2N4222A	14	N-Channel FET			

Note: T_{15} to T_{18} and T_{25} to T_{28} were unmarked transistors that appeared on commercial circuit cards. They are replaceable with the types that are listed in the table.

D(Numbers in Figures)

Type

Diodes

		
1N276	1	Ge Switch
1N916	2, 3, 4, (5-	10)* Si Switch
Operational	OA	
Amplifiers	(Numbers in Figs.)	Type
PP45U	1-7	Philbrick Researches, Inc.
Integrated	IC	
Circuits	(Number in Figs.)	
μA710C	1	Differential comparator, Fairchild semiconductor

Type	Bourns Trimpot #3282P	Bourns #3501S-1	Beckman Instrument Helipot	Dale Electronics, 4600 Series	Bourns #3852
R(Number in Figures)	1, 2, 3, 6-10, 11*, 13*, 14*	S , 4	12*	15*	16*
Adjustable Resistor	Trimmer Resistors (25 turns)	Potentiometer (10 turns)	Potentiometer (10 turns)	Motorized Potentiometer (single turn)	Potentlometer (single turn)

Positions	2	8	2	m	₽	5	12	ω	m	ч	es 25000		
Poles per Wafer		8	7	8	٦	e	г	г	8	SPDT auto return Microswitch	Switchcraft Lever-Lite Series 25000		
No. of Wafer Sections	5	7	2	2	П	7	7	П	1	SPDT au	Switche	DPDT	
S(Number in Figures)	S1	\$2	SΨ	35	36	S7	28	89	211	S3, S10B	S1 2	SloA	
Switch Type*	Wafer	=	=	=	=	=	=	=	=	Pushbutton	Lever	Toggle	

All of the wafers are made of steatite; for example Centralab type PA-7. Note:

Power Supplies* Voltage Type

Dual Supplies ±14.0(2ea.), ±6.0 Kepco DTM 2x16-0.6

Single Supply +28.0 Kepco BKF 28-0.6

Digital Voltage Source 0.0-99.999 SRC Model 3517

Miscellaneous

Туре

Card Cage* SDS Type MT-12

Muffin Fans (3 per system) Rotron 115 CFM, 115 vac.

10 turn dials (6 per system) Bourns No. H-494-3


10 turn dials* Beckman Instruments Duodial

Transformer TR-1* Triad F-25X Filament Transformer


6. Acknowledgements


The assistance of Mr. N. G. Cleveland (IBM Research Associate, Boulder, Colorado) with the initial testing and development of the system, of Mr. P. A. Mantek (Information Processing Technology Division) with the conversion of the IBM tape transport to local current control and Mr. A. W. Ericson (Information Processing Technology Division) with the testing, construction and operation of the system is gratefully acknowledged. The assistance of Miss Sharon Michael (Information Processing Technology Division) in the preparation of the manuscript is also gratefully acknowledged.

Figure 1. NBS Model II Measurement System




Signal Amplitude Read Channel Block Diagram 3 Figure






Signal Amplitude Read Channel Circuit Diagrams Figure 4.

Signal Amplitude Read Channel Circuit Diagrams Figure 5.



Signal Amplitude Read Channel Circuit Diagrams 9 Figure



40



* IBM 2401- VI System Notation

Figure 8. Write Channel Block Diagrams







Figure 10. Write Channel Circuit Diagrams




44




Switching System for the Read Channel Figure 12.





Front Panel Layout for the Model II System Figure 14.



48





Figure 16. ABC Chart Recording



U.S. DEPT. OF COMM. BIBLIOGRAPHIC DATA SHEET	1. PUBLICATION OR REPORT NO. NBS # SP260-29	2. Gov't Accession No.	3. Recipient'	s Accession No.	
4. TITLE AND SUBTITLE Calibration of NBS Secondary Standard Magnetic Tape (Computer Amplitude Reference) SRM 3200 Using the Reference Tape Amplitude Measurement "Process A" Model II		5. Publication Date June 1971 6. Performing Organization Code			
7. AUTHOR(S)			8. Performing	Crganization	
Sidney B 9. PERFORMING ORGANIZATI NATIONAL BU DEPARTMENT WASHINGTON,	10. Project/Task/Work Unit No. 3020585 11. Contract/Grant No.				
2. Sponsoring Organization Nar	ne and Address		13. Type of F Covered Fin	Report & Period	
			14. Sponsorin	g Agency Code	
operation and cal (Process A - Mode Standard Magnetic system supercedes Special Publications made with responsatory at I data that accompainments of the system of the sys	revy, mentionic here.) This publi- ibration of the NBS sig: 1 II) that is used for- Tapes (Computer Amplit- the measurement system on 260-18 (November 196- ect to a reference sign: agnetic Tape (Computer NBS. The techniques for ny each Secondary Standa dings and saturation cur	nal amplitude calibrating u ude Reference that was des 9). The sign al level deri Amplitude Ref r measuring a ard Magnetic	measuri nrecorde) SRM 32 cribed i al level ved from 'erence) nd recor Tape in	ng system d Secondary 00. This n the NBS calibration the NBS that is kept	
secondary standard	order, separated by semicolons) Averice; magnetic tape; masted; signal level calibrater unrecorded reference.	er standard; Sion; standar	saturatio <u>d refere</u> Y CLASS	on curves:	
XX UNLIMITED.				57	


FOR OFFICIAL DISTRIBUTION. DO NOT RELEASE TO NTIS.

22. Price

UNCL ASSIFIED


20. SECURITY CLASS
(THIS PAGE)

UNCL ASSIFIED











NBS TECHNICAL PUBLICATIONS

PERIODICALS

JOURNAL OF RESEARCH reports National Bureau of Standards research and development in physics, mathematics, chemistry, and engineering. Comprehensive scientific papers give complete details of the work, including laboratory data, experimental procedures, and theoretical and mathematical analyses. Illustrated with photographs, drawings, and charts.

Published in three sections, available separately:

• Physics and Chemistry

Papers of interest primarily to scientists working in these fields. This section covers a broad range of physical and chemical research, with major emphasis on standards of physical measurement, fundamental constants, and properties of matter. Issued six times a year. Annual subscription: Domestic, \$9.50; foreign, \$11.75*.

Mathematical Sciences

Studies and compilations designed mainly for the mathematician and theoretical physicist. Topics in mathematical statistics, theory of experiment design, numerical analysis, theoretical physics and chemistry, logical design and programming of computers and computer systems. Short numerical tables. Issued quarterly. Annual subscription: Domestic, \$5.00; foreign, \$6.25*.

• Engineering and Instrumentation

Reporting results of interest chiefly to the engineer and the applied scientist. This section includes many of the new developments in instrumentation resulting from the Bureau's work in physical measurement, data processing, and development of test methods. It will also cover some of the work in acoustics, applied mechanics, building research, and cryogenic engineering. Issued quarterly. Annual subscription: Domestic, \$5.00; foreign, \$6.25*.

TECHNICAL NEWS BULLETIN

The best single source of information concerning the Bureau's research, developmental, cooperative and publication activities, this monthly publication is designed for the industry-oriented individual whose daily work involves intimate contact with science and technology—for engineers, chemists, physicists, research managers, product-development managers, and company executives. Annual subscription: Domestic, \$3.00; foreign, \$4.00*.

Difference in price is due to extra cost of foreign mailing.

Order NBS publications from:

ineering

Applied Mathematics Series. Mathematical tables, manuals, and studies.

Building Science Series. Research results, test methods, and performance criteria of building materials, components, systems, and structures.

NONPERIODICALS

Handbooks. Recommended codes of engineering and industrial practice (including safety codes) developed in cooperation with interested industries, professional organizations, and regulatory bodies.

Special Publications. Proceedings of NBS conferences, bibliographies, annual reports, wall charts, pamphlets, etc.

Monographs. Major contributions to the technical literature on various subjects related to the Bureau's scientific and technical activities.

National Standard Reference Data Series. NSRDS provides quantitative data on the physical and chemical properties of materials, compiled from the world's literature and critically evaluated.

Product Standards. Provide requirements for sizes, types, quality and methods for testing various industrial products. These standards are developed cooperatively with interested Government and industry groups and provide the basis for common understanding of product characteristics for both buyers and sellers. Their use is voluntary.

Technical Notes. This series consists of communications and reports (covering both other agency and NBS-sponsored work) of limited or transitory interest.

Federal Information Processing Standards Publications. This series is the official publication within the Federal Government for information on standards adopted and promulgated under the Public Law 89–306, and Bureau of the Budget Circular A–86 entitled, Standardization of Data Elements and Codes in Data Systems.

Consumer Information Series. Practical information, based on NBS research and experience, covering areas of interest to the consumer. Easily understandable language and illustrations provide useful background knowledge for shopping in today's technological marketplace.

NBS Special Publication 305, Supplement 1, Publications of the NBS, 1968-1969. When ordering, include Catalog No. C13.10:305. Price \$4.50; foreign, \$5.75.

Superintendent of Documents Government Printing Office Washington, D.C. 20402

U.S. DEPARTMENT OF COMMERCE WASHINGTON, D.C. 20230

OFFICIAL BUSINESS

PENALTY FOR PRIVATE USE, \$300



POSTAGE AND FEES PAID

U.S. DEPARTMENT OF COMMERCE